



EKOTEKS

REPORT

030318

TEST RESULTS

ANTIBACERIAL ACTIVITY

RESULT

Over-treated

REQUIREMENT

=

This test procedure is applicable to textiles which AEM 5772/5 antimicrobial finishing.

Add 2-3 drops bromophenolblue solution onto test fabric and wait 2-3 minutes. Wash the sample with hot water and observe the colour changing. Alkaline bromophenolblue solution makes a blue complex only with quaternary amonium compound, and it can not be removed by washing. Colour severity is scaled and evaluated by the colour scale

EVALUATING

- Over-treated
- Slightly over-treated
- Good-treated
- Slightly under-treated
- Under-treated

7. G